DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 74.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-009967 Address: 333 Burma Road **Date Inspected:** 28-Oct-2009

City: Oakland, CA 94607

OSM Arrival Time: 1400 **Project Name:** SAS Superstructure **OSM Departure Time:** 1730 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Goodwin Steel, UK **Location:** Stoke-on-Trent, UK

CWI Name: N/A **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** Cable Band Castings

Summary of Items Observed:

The following report is based on METS Caltrans QA Inspector Mike Brcic's observations at Goodwin Steel Castings, Stoke-on-Trent, England, UK on 28 October 2009.

REPAIR WELDING

* GG29423-9 (B4-1F) Observed welder W. Kaminski, welder ID 629, performing Shielded Metal Arc Welding (SMAW) process using 3.2mm, E7018-1 electrode, in a 3G position. Parameters of WPS 04-0120F4A issue 4, were verified and followed; Amp average during observation was 110, voltage 23. Temperatures of casting exceeded 170° Celsius (Minimum preheat 160°C) and was below 232° Celsius, for interpass temperature (both values confirmed with temperature sticks). Excavation in work was identified as #1, "Minor", on the Weld Excavation Map.

Unless otherwise noted, all observations reported on this date appeared to be in general compliance with applicable contract documents.

Summary of Conversations:

No significant conversations took place that this Inspector was a party to.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

remedial efforts please contact Nina Choy, 1(510)385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Brcic,Michael	Quality Assurance Inspector
Reviewed By:	Edmondson,Fred	QA Reviewer